





## HUSQVARNA VITPILEN 701



\*Racing configuration

### Test conditions:

997 mBar  
19 °C

### Reference conditions:

1013 mBar  
20 °C